



Quarter End Meltables Producer Rating - Jan-Mar 2015
 Material Type:40

Code	Receipts	Category: Points:	A 8	B 9	C 5	D 12	E1 8	F 8	G 10	H 5	I 5	J 25	K 5	Total 100
P118	8		8.0	9.0	5.0	.0	8.0	8.0	10.0	5.0	.0	25.0	.0	78.0
P949	3		8.0	9.0	5.0	12.0	8.0	8.0	10.0	5.0	.0	25.0	.0	90.0
P012	3		8.0	9.0	5.0	8.0	8.0	8.0	10.0	5.0	5.0	25.0	5.0	96.0
P951	3		8.0	9.0	5.0	8.0	8.0	8.0	10.0	5.0	5.0	25.0	5.0	96.0
P801	4		8.0	9.0	5.0	9.0	8.0	8.0	10.0	5.0	5.0	25.0	5.0	97.0
P135	160		8.0	9.0	5.0	10.5	8.0	8.0	10.0	5.0	5.0	25.0	5.0	98.5
P256	36		8.0	9.0	5.0	10.7	8.0	8.0	10.0	5.0	5.0	25.0	5.0	98.7
P558	43		8.0	9.0	4.4	11.4	8.0	8.0	10.0	5.0	5.0	25.0	5.0	98.9
P100	212		8.0	9.0	5.0	11.2	8.0	8.0	10.0	5.0	5.0	25.0	5.0	99.2
P027	85		8.0	9.0	5.0	11.3	8.0	8.0	10.0	5.0	5.0	25.0	5.0	99.3
P260	397		8.0	9.0	5.0	11.4	8.0	8.0	10.0	5.0	5.0	25.0	5.0	99.4
P013	44		8.0	9.0	5.0	11.5	8.0	8.0	10.0	5.0	5.0	25.0	5.0	99.5
P723	252		8.0	9.0	5.0	11.9	8.0	8.0	10.0	5.0	5.0	25.0	5.0	99.9
P149	246		8.0	9.0	5.0	12.0	8.0	8.0	10.0	5.0	5.0	25.0	5.0	100.0
P277	1		8.0	9.0	5.0	12.0	8.0	8.0	10.0	5.0	5.0	25.0	5.0	100.0
P296	1		8.0	9.0	5.0	12.0	8.0	8.0	10.0	5.0	5.0	25.0	5.0	100.0
P754	1		8.0	9.0	5.0	12.0	8.0	8.0	10.0	5.0	5.0	25.0	5.0	100.0

A - Bill of Lading Data
 B - Visual
 C - Chemical Analysis
 D - Concession
 E1 - Sow Quality

F - Sample Preparation, Quality
 G - Non-Conforming Product / Reject
 H - Receiving Sample Buttons
 I - Required Elements Listed on COA
 J - Safety

K - Using Melts for Data Upload